

DIAREX blade G3 for granite and quartzite

Granite

| Diameter Ø | Rpm (1/min) |
|---------------|----------------|
| 400 mm | 1600 - 2000 |
| 450 mm | 1400 - 1800 |
| 500 mm | 1300 - 1600 |

| | |
|-----------------------|-----------------|
| Feed Speed full cut | 2,5 - 4,5 m/min |
| Feed Speed mitre cuts | 0,8 - 1,5 m/min |

Quartzite

| Diameter Ø | Rpm (1/min) |
|---------------|----------------|
| 400 mm | 1100 - 1300 |
| 450 mm | 1000 - 1150 |
| 500 mm | 900 - 1050 |

| | |
|-----------------------|-----------------|
| Feed Speed full cut | 1,5 - 2,5 m/min |
| Feed Speed mitre cuts | 0,8 - 1,2 m/min |



König Tool Tipp

- Regularly check the water supply and water quantity.
- The water should hit the core and segments at an angle of approx. 45°.